


Tree not surveyed,
location to be
confirmed

Tree protection fence to be
placed as close as possible
from the excavation line.



LEGEND

- TREE PROTECTION ZONE
- NO-BUILD ZONE
- TREE PROTECTION FENCE
- TREE TO BE RETAINED
- UN-SURVEYED TREE
- ✕ TREE TO BE REMOVED

NOTES

1. The location of un-surveyed trees on this plan is approximate. Their location and ownership cannot be confirmed without being surveyed by a Registered BC Land Surveyor.
2. All tree protection fencing must be built to the relevant municipal bylaw specifications. The dimensions shown are from the outer edge of the stem of the tree.
3. The tree protection zone shown is a graphical representation of the critical root zone, measured from the outer edge of the stem of the tree ($\frac{1}{2}$ the trees' diameter) was added to the graphical tree protection circles to accommodate the survey point being in the center of the tree).
4. Any construction activities or grade changes within the Root Protection Zone must be approved by the project arborist.
5. This plan is based on a topographic and tree location survey provided by the owners' Registered British Columbia Land Surveyor (BCLS) and layout drawings provide by the owners' Engineer (P Eng).
6. This plan is provided for context only, and is not certified as to the accuracy of the location of features or dimensions that are shown on this plan. Please refer to the original survey plan and engineering plans.

REFERENCE DRAWINGS

1. Base Survey by: